



MOTOR WIRING DIAGRAM



NOTES:

- 1. INTERCHANGE ANY TWO LINE LEADS TO REVERSE ROTATION.
- 2. OPTIONAL THERMOSTATS ARE PROVIDED WHEN
- 3. ACTUAL NUMBER OF INTERNAL PARALLEL CIRCUITS MAY BE A MULTIPLE OF THOSE SHOWN ABOVE.
- 4. LEAD COLORS ARE OPTIONAL. LEADS MUST ALWAYS BE NUMBERED AS SHOWN.

FAN WIRING DIAGRAM



| MASS | 91.145 KG [200.94 LBS] |
|---------------|------------------------|
| SPEED | 1750 |
| FAN VOLTAGE | 460 VAC 3~ |
| FAN CURRENT | 0.24A |
| MOTOR VOLTAGE | 460VAC 3~ |
| MOTOR CURRENT | 1.2 A |

CONFIDENTIAL. THIS DOCUMENT AND THE DATA DISCLOSED HEREIN OR HEREWITH IS NOT TO BE REPRODUCED, USED, OR DISCLOSED IN WHOLE OR IN PART TO ANYONE WITHOUT THE PERMISSION OF AIR SQUARED, INC.

LAYOUT DRAWING

DIMENSIONS ARE IN MM SHEET 2 OF 2 | SCALE: 1:10

SIZE PART NO. 16H034A-B02